



# the play inspection company

Annual Inspection

Pendle Borough Council

Salterforth

Moor Lane, Salterforth, Barnoldswick, Lancashire, BB18  
5SP



**API** Associate

Unit 5, Glenmore Business Park, Blackhill Road, Poole, Dorset, BH16 6NL  
t- 01202 590675 e- info@playinspections.co.uk

[www.playinspections.co.uk](http://www.playinspections.co.uk)

Powered by:  
**the play ►  
inspection app**

By the play inspection company

## Table 1

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual Outdoor/ Fully enclosed Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	✓	✓ [1]
6.1 d) Overall levels of safety of foundations (see note 1)	✓	✓ [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	✓	✓ [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	✓	✓ [3]
6.1 d) Effects of weather	✓	✓
6.1 d) Presence of rot, decay or corrosion (see note 1)	✓	✓ [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	✓	✓ [4]
6.1 d) Excavation or dismantling/additional measures	✓	✗
6.2.1 Assessment of glass reinforced plastics (see note 5)	✓	✓ [5]
6.2.1 Inspection of one post equipment (see note 1)	✓	✓ [1]
6.2.4 Undertaking the Operators inspection protocol	✓	✗

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant standards.

[1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.

[2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.

[3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.

[4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance

[5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

# Risk Assessment Matrix

		Scores in the report are multiplication factors of Likelihood x Severity						
		Severity>>						
Likelihood	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)
	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)
			Very Low	Low	Moderate	High	Very High	
			1	2	3	4	5	
			No injury likely e.g. damaged or soiled clothing, minor bruising, grazes	Minor injury, laceration or bruising requiring first aid only	Injury requiring medical intervention e.g. cuts requiring stitches	Serious injury including concussions or fracture of long bones	Severe injury involving a potential life changing injury or fatality	
			Severity>>					
			Note 1: The total risk scores included within our reports are a multiplication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity (3).					
			Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.					

**Equipment has been assessed to the following standards where relevant:**

- BS EN 1176 Parts 1-11 (Playground equipment and surfacing)
- BS EN 14974 (Facilities for users of roller sports equipment)
- BS EN 15312 (Free access multi-sports equipment)
- BS EN 16899 (Parkour Equipment)
- BS EN 16630 (Outdoor Fitness Equipment).



The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675

## Salterforth

Inspection Ref: 1185265

Site Ref: 9410

Customer Order: N/A

Inspected: 10-September-2020 - 10:32 by Lyn Williams RPII Annual Inspector

Risk Assessment: 10 Low Risk



**Location:**

The site is located in an area of public open space and is overlooked by a number of properties in the local community.

**Disabled Access:**

Some accessible features; an area that presents difficulties to the majority of people with disabilities but in favourable circumstances and certainly in partnership can be accessed.



The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675

**i 8 - Low Risk**

**Item:** Site General  
**Manufacturer:** Owner/Operator  
**Surface Type:** N/A  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A

**Total Findings:** 2

**Finding 1**  
Sand has migrated onto the impact attenuating surface - Remove and maintain

**Finding 2**  
The adjacent grassed areas have encroached onto the impact attenuation surface - Cut back and maintain the grass



**i 5 - Very Low Risk**

**Item:** Sign  
**Manufacturer:** Not Identified  
**Surface Type:** N/A  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A

**Total Findings:** 1

**Finding 1**  
BS EN 1176 Part 7 recommends that signage shall include the site name / address - Provide additional information





**i** 8 - Low Risk

**Item:** Gate - Self Closing  
**Manufacturer:** Owner/Operator  
**Surface Type:** Bitmac  
**Item Quantity:** 2  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A

**Total Findings:** 3

**Finding 1**  
One gate has been padlocked shut - Consider removing the padlock

**Finding 2**  
There are openings that are less than 12mm that could trap or crush fingers - Where possible a 12mm gap should be maintained on both sides or between the gate leafs

**Finding 3**  
The gate is closing too quickly (less than 4 seconds) - Take corrective action to ensure that the gate closes in 4-8 seconds



**i** 6 - Low Risk

**Item:** Gate - Maintenance  
**Manufacturer:** Obra  
**Surface Type:** Bitmac  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A

**Total Findings:** 1

**Finding 1**  
There is no padlock on the maintenance gate - Provide a padlock to secure the gate





8 - Low Risk

**Item:** Stone Wall  
**Manufacturer:** Owner/Operator  
**Surface Type:** N/A  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A

**Total Findings:** 1



**Finding 1**

There is algae or moss on the wall - Clean and treat appropriately

8 - Low Risk

**Item:** Fencing - Timber  
**Manufacturer:** Owner/Operator  
**Surface Type:** N/A  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A

**Total Findings:** 1



**Finding 1**

There are projecting bolt thread(s) present - Remove excess thread length and deburr or provide cap



**i 8 - Low Risk**

**Item:** Bench  
**Manufacturer:** Owner/Operator  
**Surface Type:** Bitmac  
**Item Quantity:** 7  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A

**Total Findings:** 2

**Finding 1**  
There is/are bolt cap covers missing or damaged on the item - Replace missing or damaged bolt cap covers

**Finding 2**  
There is or are fixings missing on the bench and the bench can be lifted off the ground anchor bolts - Replace all missing fixings



**i 6 - Low Risk**

**Item:** Picnic Table  
**Manufacturer:** Owner/Operator  
**Surface Type:** Concrete  
**Item Quantity:** 1  
**Equipment Compliance:** N/A  
**Surface Area Compliance:** N/A

**Total Findings:** 1

**Finding 1**  
There is minor damage to the bench - Monitor





The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675

**i 4 - Very Low Risk**

<b>Item:</b>	Litter Bin
<b>Manufacturer:</b>	Owner/Operator
<b>Surface Type:</b>	Grass
<b>Item Quantity:</b>	3
<b>Equipment Compliance:</b>	N/A
<b>Surface Area Compliance:</b>	N/A

**Total Findings:** 1

**Finding 1**  
This item is satisfactory - no work required -

**i 6 - Low Risk**

<b>Item:</b>	Goalmouth and Basketball Post
<b>Manufacturer:</b>	Parkdale Play & Leisure Ltd
<b>Surface Type:</b>	Tarmac
<b>Item Quantity:</b>	1
<b>Equipment Compliance:</b>	No
<b>Surface Area Compliance:</b>	Yes
<b>Life Expectancy:</b>	5 -10 Years
<b>Total Findings:</b>	3

**Finding 1**  
A clearly visible facility sign should be provided in a prominent position with the wording as detailed BS EN 15312- the equipment is not intended for children less than 3 years old- the warning - Do not climb on the framework or nets- the warning - Do not hang on the ring (if provided)- the warning - Do not wear rings or other jewellery- name and telephone number of the administrator- number to call in case of accident - Provide signage to BS EN 15312

**Finding 2**  
There is/are finger entrapments in the mesh openings and the item fails to meet the requirements of BS EN 15312 Clause 4.4.2.2 Entrapment of fingers - Monitor - No remedial work recommended

**Finding 3**  
The paint is flaking off the metalwork - Rub down and re-paint



The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675

**8 - Low Risk**

<b>Item:</b>	Football Goal	
<b>Manufacturer:</b>	Harrod	
<b>Surface Type:</b>	Grass	
<b>Item Quantity:</b>	2	
<b>Equipment Compliance:</b>	N/A	
<b>Surface Area Compliance:</b>	N/A	
<b>Life Expectancy:</b>	3 - 5 Years	
<b>Total Findings:</b>	3	

**Finding 1**  
The item is loose in its foundations - Reinstall item to secure

**Finding 2**  
There is algae or moss on the surface of the equipment -  
Clean and treat appropriately

**Finding 3**  
NB: We have undertaken a maintenance inspection only of  
the football goal(s); full load testing falls outside the scope  
of our inspection. - Implement load testing as required

**6 - Low Risk**

<b>Item:</b>	Spring Crazy Daisy	
<b>Manufacturer:</b>	Not Identified	
<b>Surface Type:</b>	Grass	
<b>Item Quantity:</b>	1	
<b>Equipment Compliance:</b>	Yes	
<b>Surface Area Compliance:</b>	Yes	
<b>Life Expectancy:</b>	5 -10 Years	
<b>Total Findings:</b>	1	

**Finding 1**  
The item is slightly loose in its foundations - Monitor for any further deterioration and repair as required



## 10 - Low Risk

**Item:** 2 Bay 4 Seat (Flat)  
**Manufacturer:** Wicksteed Playgrounds  
**Surface Type:** Rubber Tiles  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes  
**Life Expectancy:** 5 -10 Years  
**Total Findings:** 3



### Finding 1

The bushes are showing signs of wear - Monitor for any further deterioration and replace as required

### Finding 2

There is some wear to the shackles. - Monitor for any further deterioration and replace when 40% worn

### Finding 3

The seat is damaged and requires replacing - Replace damaged seat



## 6 - Low Risk

**Item:** Spring Bike  
**Manufacturer:** Ledon  
**Surface Type:** Wet Pour  
**Item Quantity:** 1  
**Equipment Compliance:** No  
**Surface Area Compliance:** Yes  
**Life Expectancy:** 5 -10 Years  
**Total Findings:** 2



### Finding 1

The end of handgrips and/or footrests have a cross section of less than 15cm<sup>2</sup> and fail to meet the requirements of BS EN 1176 Part 6 - Monitor - No remedial work recommended

### Finding 2

The paintwork on the spring has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint



**6 - Low Risk**

<b>Item:</b>	Spring See-Saw
<b>Manufacturer:</b>	Fahr Industries
<b>Surface Type:</b>	Wet Pour
<b>Item Quantity:</b>	1
<b>Equipment Compliance:</b>	Yes
<b>Surface Area Compliance:</b>	Yes
<b>Life Expectancy:</b>	5 -10 Years
<b>Total Findings:</b>	1

**Finding 1**

The paintwork on the spring has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint



**6 - Low Risk**

<b>Item:</b>	1 Bay 2 Seat (Cradle)
<b>Manufacturer:</b>	Wicksteed Playgrounds
<b>Surface Type:</b>	Wet Pour
<b>Item Quantity:</b>	1
<b>Equipment Compliance:</b>	Yes
<b>Surface Area Compliance:</b>	No
<b>Life Expectancy:</b>	5 -10 Years
<b>Total Findings:</b>	3

**Finding 1**

The bushes are showing signs of wear - Monitor for any further deterioration and replace as required

**Finding 2**

There is some wear to the shackles. - Monitor for any further deterioration and replace when 40% worn

**Finding 3**

The surfacing dimensions are short and do not meet with the requirements of the current applicable standard - Monitor - no remedial action recommended





**i 6 - Low Risk**

<b>Item:</b>	Sand Box
<b>Manufacturer:</b>	Not Identified
<b>Surface Type:</b>	Sand
<b>Item Quantity:</b>	1
<b>Equipment Compliance:</b>	Yes
<b>Surface Area Compliance:</b>	N/A

**Total Findings:** 1



**Finding 1**  
Sand is migrating to adjacent surfaces - Provide appropriate sand retention

**i 6 - Low Risk**

<b>Item:</b>	Multi Play (Junior)
<b>Manufacturer:</b>	Parkdale Play & Leisure Ltd
<b>Surface Type:</b>	Wet Pour
<b>Item Quantity:</b>	1
<b>Equipment Compliance:</b>	No
<b>Surface Area Compliance:</b>	Yes
<b>Life Expectancy:</b>	5 -10 Years
<b>Total Findings:</b>	5

**Finding 1**  
There are a number of dents in the slide surface - Monitor for any further deterioration and repair as required

**Finding 2**  
The ropes/nets are worn/damaged in places - Monitor for any further deterioration and repair or replace as required

**Finding 3**  
There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required

**Finding 4**  
The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint

**Finding 5**  
The connecting links are in excess of 8.6mm and less than 12mm and fail the requirements of BS EN 1176 Part 1; clause 4.2.13, Chains - Monitor use and replace with compliant links at the next maintenance cycle





4 - Very Low Risk

**Item:** Sand Play Unit  
**Manufacturer:** Hags  
**Surface Type:** Sand  
**Item Quantity:** 1  
**Equipment Compliance:** Yes  
**Surface Area Compliance:** N/A  
**Life Expectancy:** 5 -10 Years  
**Total Findings:** 1

**Finding 1**  
This item is satisfactory - no work required -



4 - Very Low Risk

**Item:** Multi Play (Toddler)  
**Manufacturer:** Hags  
**Surface Type:** Wet Pour  
**Item Quantity:** 1  
**Equipment Compliance:** Yes  
**Surface Area Compliance:** Yes

**Total Findings:** 1

**Finding 1**  
This item is satisfactory - no work required -





## Findings information

8 - Low Risk (Finding 1)	
<b>Item:</b> Ancillary Items - Site General	<b>Risk Level:</b> L - Low Risk
<b>Manufacturer:</b> Owner/Operator	<b>Surface:</b> N/A
	
<b>Finding:</b> Sand has migrated onto the impact attenuating surface	<b>Action:</b> Remove and maintain
8 - Low Risk (Finding 2)	
<b>Item:</b> Ancillary Items - Site General	<b>Risk Level:</b> L - Low Risk
<b>Manufacturer:</b> Owner/Operator	<b>Surface:</b> N/A
	
<b>Finding:</b> The adjacent grassed areas have encroached onto the impact attenuation surface	<b>Action:</b> Cut back and maintain the grass



The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675




#### 5 - Very Low Risk (Finding 1)

**Item:** Ancillary Items - Sign  
**Manufacturer:** Not Identified

**Risk Level:** V - Very Low Risk  
**Surface:** N/A



**Finding:** BS EN 1176 Part 7 recommends that signage shall include the site name / address  
**Action:** Provide additional information



**Finding:** One gate has been padlocked shut

**Action:** Consider removing the padlock



**i 8 - Low Risk (Finding 2)**

<b>Item:</b> Ancillary Items - Gate - Self Closing <b>Manufacturer:</b> Owner/Operator	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Bitmac
---	---



**Finding:** There are openings that are less than 12mm that could trap or crush fingers

**Action:** Where possible a 12mm gap should be maintained on both sides or between the gate leafs

**i 8 - Low Risk (Finding 3)**

<b>Item:</b> Ancillary Items - Gate - Self Closing <b>Manufacturer:</b> Owner/Operator	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Bitmac
---	---



**Finding:** The gate is closing too quickly (less than 4 seconds)


**Action:** Take corrective action to ensure that the gate closes in 4-8 seconds



### 6 - Low Risk (Finding 1)

**Item:** Ancillary Items - Gate - Maintenance  
**Manufacturer:** Obra

**Risk Level:** L - Low Risk  
**Surface:** Bitmac



**Finding:** There is no padlock on the maintenance gate

**Action:** Provide a padlock to secure the gate



### 8 - Low Risk (Finding 1)

**Item:** Ancillary Items - Stone Wall  
**Manufacturer:** Owner/Operator

**Risk Level:** L - Low Risk  
**Surface:** N/A




**Finding:** There is algae or moss on the wall

**Action:** Clean and treat appropriately



**i 8 - Low Risk (Finding 1)**

<b>Item:</b> Ancillary Items - Fencing - Timber <b>Manufacturer:</b> Owner/Operator	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> N/A
--	--



**Finding:** There are projecting bolt thread(s) present

**Action:** Remove excess thread length and deburr or provide cap

**i 4 - Very Low Risk (Finding 1)**

<b>Item:</b> Ancillary Items - Bench <b>Manufacturer:</b> Owner/Operator	<b>Risk Level:</b> V - Very Low Risk <b>Surface:</b> Bitmac
---	--



**Finding:** There is/are bolt cap covers missing or damaged on the item

**Action:** Replace missing or damaged bolt cap covers



The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675



### 8 - Low Risk (Finding 2)

**Item:** Ancillary Items - Bench  
**Manufacturer:** Owner/Operator

**Risk Level:** L - Low Risk  
**Surface:** Bitmac



**Finding:** There is or are fixings missing on the bench and the bench can be lifted off the ground anchor bolts


**Action:** Replace all missing fixings



### 6 - Low Risk (Finding 1)

**Item:** Ancillary Items - Picnic Table  
**Manufacturer:** Owner/Operator

**Risk Level:** L - Low Risk  
**Surface:** Concrete



**Finding:** There is minor damage to the bench

**Action:** Monitor



The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675

5 - Very Low Risk (Finding 1)			
<b>Item:</b>	Multi Use Games Area - Goalmouth and Basketball Post	<b>Risk Level:</b>	V - Very Low Risk
<b>Manufacturer:</b>	Parkdale Play & Leisure Ltd	<b>Surface:</b>	Tarmac
 A photograph of a multi-use games area. It features a basketball hoop mounted on a blue-painted metal frame. In front of the hoop is a red and yellow padded safety net. The background shows a grassy field and some trees.			 A close-up photograph of a basketball hoop. The backboard is white with the letters "PPL" printed on it. The hoop is mounted on a black pole.
<b>Finding:</b> A clearly visible facility sign should be provided in a prominent position with the wording as detailed BS EN 15312- the equipment is not intended for children less than 3 years old- the warning - Do not climb on the framework or nets- the warning - Do not hang on the ring (if provided)- the warning - Do not wear rings or other jewellery- name and telephone number of the administrator- number to call in case of accident			<b>Action:</b> Provide signage to BS EN 15312



The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675



### 5 - Very Low Risk (Finding 2)

**Item:** Multi Use Games Area - Goalmouth and Basketball Post  
**Manufacturer:** Parkdale Play & Leisure Ltd



**Risk Level:** V - Very Low Risk  
**Surface:** Tarmac



**Finding:** There is/are finger entrapments in the mesh openings and the item fails to meet the requirements of BS EN 15312 Clause 4.4.2.2 Entrapment of fingers

**Action:** Monitor - No remedial work recommended

### 6 - Low Risk (Finding 3)

**Item:** Multi Use Games Area - Goalmouth and Basketball Post  
**Manufacturer:** Parkdale Play & Leisure Ltd



**Risk Level:** L - Low Risk  
**Surface:** Tarmac




**Finding:** The paint is flaking off the metalwork

**Action:** Rub down and re-paint



**8 - Low Risk (Finding 1)**

<b>Item:</b> Multi Use Games Area - Football Goal <b>Manufacturer:</b> Harrod	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Grass
--	--



**Finding:** The item is loose in its foundations

**Action:** Reinstall item to secure

**6 - Low Risk (Finding 2)**

<b>Item:</b> Multi Use Games Area - Football Goal <b>Manufacturer:</b> Harrod	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Grass
--	--



**Finding:** There is algae or moss on the surface of the equipment

**Action:** Clean and treat appropriately



**i** 0 - Risk Assessment not Undertaken (Finding 3)

**Item:** Multi Use Games Area - Football Goal  
**Manufacturer:** Harrod      **Risk Level:** N - Risk Assessment not Undertaken  
**Surface:** Grass



**Finding:** NB: We have undertaken a maintenance inspection only of the football goal(s); full load testing falls outside the scope of our inspection.

**Action:** Implement load testing as required

**i** 6 - Low Risk (Finding 1)

**Item:** Rocking Equipment - Spring Crazy Daisy  
**Manufacturer:** Not Identified      **Risk Level:** L - Low Risk  
**Surface:** Grass



**Finding:** The item is slightly loose in its foundations

**Action:** Monitor for any further deterioration and repair as required



**4 - Very Low Risk (Finding 1)**

<b>Item:</b> Swings - 2 Bay 4 Seat (Flat) <b>Manufacturer:</b> Wicksteed Playgrounds	<b>Risk Level:</b> V - Very Low Risk <b>Surface:</b> Rubber Tiles
---	--



**Finding:** The bushes are showing signs of wear

**Action:** Monitor for any further deterioration and replace as required

**6 - Low Risk (Finding 2)**

<b>Item:</b> Swings - 2 Bay 4 Seat (Flat) <b>Manufacturer:</b> Wicksteed Playgrounds	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Rubber Tiles
---	---



**Finding:** There is some wear to the shackles.

**Action:** Monitor for any further deterioration and replace when 40% worn



**i** 10 - Low Risk (Finding 3)

<b>Item:</b> Swings - 2 Bay 4 Seat (Flat) <b>Manufacturer:</b> Wicksteed Playgrounds	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Rubber Tiles
---	---



**Finding:** The seat is damaged and requires replacing

**Action:** Replace damaged seat

**i** 6 - Low Risk (Finding 1)

<b>Item:</b> Rocking Equipment - Spring Bike <b>Manufacturer:</b> Ledon	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Wet Pour
--	---



**Finding:** The end of handgrips and/or footrests have a cross section of less than 15cm<sup>2</sup> and fail to meet the requirements of BS EN 1176 Part 6

**Action:** Monitor - No remedial work recommended



The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675

**i** 6 - Low Risk (Finding 2)

<b>Item:</b> Rocking Equipment - Spring Bike <b>Manufacturer:</b> Ledon	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Wet Pour
--	---



**Finding:** The paintwork on the spring has been damaged or **Action:** Treat any rusting components and repaint worn exposing the metal underneath which is rusting

**i** 6 - Low Risk (Finding 1)

<b>Item:</b> Rocking Equipment - Spring See-Saw <b>Manufacturer:</b> Fahr Industries	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Wet Pour
---	---



**Finding:** The paintwork on the spring has been damaged or **Action:** Treat any rusting components and repaint worn exposing the metal underneath which is rusting



**i** 4 - Very Low Risk (Finding 1)

<b>Item:</b> Swings - 1 Bay 2 Seat (Cradle) <b>Manufacturer:</b> Wicksteed Playgrounds	<b>Risk Level:</b> V - Very Low Risk <b>Surface:</b> Wet Pour
---	--




**Finding:** The bushes are showing signs of wear

**Action:** Monitor for any further deterioration and replace as required

**i** 6 - Low Risk (Finding 2)

<b>Item:</b> Swings - 1 Bay 2 Seat (Cradle) <b>Manufacturer:</b> Wicksteed Playgrounds	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Wet Pour
---	---



**Finding:** There is some wear to the shackles.

**Action:** Monitor for any further deterioration and replace when 40% worn



5 - Very Low Risk (Finding 3)	
<b>Item:</b> Swings - 1 Bay 2 Seat (Cradle) <b>Manufacturer:</b> Wicksteed Playgrounds	<b>Risk Level:</b> V - Very Low Risk <b>Surface:</b> Wet Pour
	
<b>Finding:</b> The surfacing dimensions are short and do not meet with the requirements of the current applicable standard	<b>Action:</b> Monitor - no remedial action recommended
6 - Low Risk (Finding 1)	
<b>Item:</b> Activity Equipment - Sand Box <b>Manufacturer:</b> Not Identified	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Sand
	
<b>Finding:</b> Sand is migrating to adjacent surfaces	<b>Action:</b> Provide appropriate sand retention



The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675



#### 4 - Very Low Risk (Finding 1)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Parkdale Play & Leisure Ltd



**Risk Level:** V - Very Low Risk  
**Surface:** Wet Pour



**Finding:** There are a number of dents in the slide surface

**Action:** Monitor for any further deterioration and repair as required



#### 6 - Low Risk (Finding 2)

**Item:** Activity Equipment - Multi Play (Junior)  
**Manufacturer:** Parkdale Play & Leisure Ltd



**Risk Level:** L - Low Risk  
**Surface:** Wet Pour



**Finding:** The ropes/nets are worn/damaged in places

**Action:** Monitor for any further deterioration and repair or replace as required



**6 - Low Risk (Finding 3)**

<b>Item:</b> Activity Equipment - Multi Play (Junior) <b>Manufacturer:</b> Parkdale Play & Leisure Ltd	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Wet Pour
---	---



**Finding:** There is some evidence of rot in the timber

**Action:** Monitor for any further deterioration and replace as required

**6 - Low Risk (Finding 4)**

<b>Item:</b> Activity Equipment - Multi Play (Junior) <b>Manufacturer:</b> Parkdale Play & Leisure Ltd	<b>Risk Level:</b> L - Low Risk <b>Surface:</b> Wet Pour
---	---



**Finding:** The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting

**Action:** Treat any rusting components and repaint



The Play Inspection Company Ltd  
Unit 5 Glenmore Business Park  
Blackhill Road  
Poole  
Dorset  
BH16 6NL  
01202 590675

**i** 5 - Very Low Risk (Finding 5)

<b>Item:</b> Activity Equipment - Multi Play (Junior) <b>Manufacturer:</b> Parkdale Play & Leisure Ltd	<b>Risk Level:</b> V - Very Low Risk <b>Surface:</b> Wet Pour
---	--



**Finding:** The connecting links are in excess of 8.6mm and less than 12mm and fail the requirements of BS EN 1176 Part 1; clause 4.2.13, Chains

**Action:** Monitor use and replace with compliant links at the next maintenance cycle